

Fig 1





Fig 2a






Fig 3




Fig 4

Plough

Lay Barge




Fig 5




Fig 6

FIG 7




FIG 8




FIG 9




FIG 10




FIG 11




FIG 13




FIG 14





FIG 15



[illegible]

FIG 16




FIG 18





FIG 19






FIG 20

FIG 21





FIG 22



Internal duct


320

Flowing water



Water propelled cable

Fig. 23







Fig 24

Fig. 25







Fig 26

Fig. 27






Fig 28




Fig 29

FOOT 1288660




Fig 30




Fig 31

FOOT-12888660




Fig 32




Fig 33




Fig 34

System Name	Pre-Repair Burial Status	Date of Fault	Seabed Type	Type of Fault	Water Depth	Type of Armour	Repair Ship
CANUS 1	Surface Laid	1-Mar-98	Sand	Dredging	65 ft	Double Armor	Sir Eric Sharp
TAT 7	Surface Laid	18-Apr-86	Sand	Anchor	90 ft	Unknown	Mercury
TAT 7	Surface Laid	10-Aug-89	Sand	Fishing	175 ft	Lightweight	C.S. Alert
TAT 7	Unknown	9-Aug-93	Unknown	Repeater	160 ft	Unknown	Global Mariner
TAT 8	Postlay Buried	10-Aug-93	Unknown	Unknown	90 ft	LWP	Global Mariner

Fig 35




FIG 37




FIG 38

FOOT FEED




Fig. 40




Fig. 41




Fig. 42

Figure 43




Figure 44





Figure 45



PROJECT T2888660

Figure 46




Figure 47




Figure 48




Figure 49




Figure 50




Fig. 51




Fig. 52





Fig. 53



100216-1233560